



90 Day Inspection - BIT CA

So Cal Tow Equipment / EQ4403

Complete

Score	38 / 40 (95%)	Flagged items	1	Actions	0
Site conducted	1335 N Knollwood Cir Anaheim CA 92801 United States (33.85428498043794, -117.97997137591567)				
Company Name	So Cal Tow Equipment				
Conducted on	02/14/2025				
Prepared By	Ricky Jimenez				
Unit Number	EQ4403				

Flagged items


1 flagged

Inspection Data

4. Windshield wipers, window cracks

Non-Compliant

Vehicle Info		1 / 1 (100%)
Year		2018
Make		Hino
VIN Number		5PVNJ8JN8K4S53672
Mileage		226335

Inspection Data		1 flagged, 36 / 38 (94.74%)
1. Fire extinguisher and reflective warning devices	Compliant	
2. Horn, defroster, gauges, odometer, and speedometer	Compliant	
3. Mirrors and supports	Compliant	
4. Windshield wipers, window cracks	Non-Compliant	
<div>What is the defect?</div> <div>Windshield cracked</div> <div></div> <div>Photo 1</div>		
5. All lights, signals, reflectors, mudflaps	Compliant	
6. Electrical wiring-condition and protection	Compliant	
7. Batteries-water level, terminals, and cables	Good	
<div>Battery cover not installed. It's laying in the bed.</div>		
* 8. Warning devices-air, oil, temperature, anti skid, and/or vacuum	Compliant	
9. Radiator and water hoses- coolant level, condition, and/or leaks	Good	
* 10. Belts-compressor, fan, water pump, and/or alternator	Good	
* 11. Air hoses and tubing-leaks, condition, and/or protection	Compliant	
12. Fuel system-tank, hoses, tubing, and/or pump; leaks	Compliant	
13. Exhaust system, manifolds, piping, muffler; leaks and/or condition	Compliant	
14. Engine-mounting, excessive grease and/or oil	Good	
15. Clutch adjustment-free play	N/A	
16. Air filter, throttle linkage	Good	

17. Starting and charging system	Good
* 19. Hydraulic brake system-adjustment, components, and/or condition	N/A
* 20. Hydraulic master cylinder level, leaks, and/or condition	N/A
* 21. Hoses and tubing-condition and protection	Compliant
* 22. Air brake system-adjustment, components, and/or condition	Compliant
* 23. 1 minute air or vacuum loss test	Compliant
* 24. Air compressor governor cut-in and cut-out pressures (85-130)	Compliant
* 25. Primary air tank-drain and test check valve	Compliant
* 26. Other air tanks-drain and check for contamination; securement	Compliant
* 27. Tires-tread depth, inflation, and condition	Compliant
* 28. Wheels, lug nuts, and studs-cracks, looseness, and/or condition	Compliant
* 29. Parking brake-able to hold the vehicle	Compliant
* 30. Emergency stopping system-labeled and operative	Compliant
*31. Brakes release after complete loss of service air	Compliant
* 32. Steering system-mounting, free lash, and components	Compliant
* 33. Steering arms, drag links, and/or tie rod ends	Compliant
* 34. Connecting devices- fifth wheel, pintle hitch, and/or safety devices*	Compliant
* 35. Suspension system-springs, shackles, u-bolts, and/or torque rods	Compliant
* 36. Frame and cross members-cracks and/or condition	Compliant
37. Drive shaft, universal joints, and/or guards	Compliant
38. Transmission and differential-mounting, leaks, and/or condition	Compliant

39. Wheel seals-leaks and/or condition	Compliant
40. Under carriage-clean and secure	Good

Signature Page

Please Sign

A handwritten signature in black ink, appearing to read 'Ricky Jimenez', is displayed on a light gray rectangular background.

Ricky Jimenez
02/14/2025 2:02 PM PST

Media summary



Photo 1